Cambuslang RFC

House Convenor's Report – Period to Jan 2026

Current Building Repair Works:

Area	Work Scope	Comment
Members Bar	Carpet upgrade	Carpet fitter has been engaged and prices are imminent for either 1. New one-piece carpet of requisite industrial quality OR 2. New joints on existing carpet. Ongoing work to generate proposal for committee to consider
	Door Closer	Install new door closer
Loft Access	Improve access	Fitting of loft ladder – Scott Chalmers will make modifications to the current wooden loft hatch. The new plastic type hatch is not compatible and will need to be returned. Ongoing
Changing Room 6	Replace Toilet Cistern	Toilet out-of-use, broken cistern. Not essential, rarely used
LED Lighting upgrade	Grant funding - secured	Discussion required at Committee – possible subcommittee?
Showers	Operating Regime	Tanya is working to an agreed weekly procedure but this to be documented
Fire Alarm	Testing	Internal testing regime to be documented. 6-month inspection has been undertaken by Highlander in Oct 2022
Upstairs Blinds	Assess	Windows have been measured – ongoing work to generate proposal for committee to consider
Heating System	Download App	Download app to allow control of heating and hot water remotely – Scott and Brian - ongoing